

U. S. Steel Clainton Works 400 State Street Clainton, PA 15025-1865

May 8, 1995

Director, Air Toxics and Radiation Division U. S. EPA Region III 841 Chestnut Street Philadelphia, PA 19107

SUBJECT: 1994 Summary Reports - Leak Detection and Repair of Equipment in Benzene Service USS Clairton Works - Clairton, Pennsylvania

Dear Sir or Madam:

Please fine enclosed two copies of the benzene NESHAPS monitoring reports for 1994.

These reports summarize the results of the monitoring of equipment in benzene service for fugitive emissions at USS Clairton Works facility located in Clairton, Pennsylvania. These reports have been prepared by Advanced Technology Systems, Inc. to satisfy the requirements promulgated by 40 CFR 61 Subparts L and V.

If you have any questions regarding this package, please call me at (412) 233-1101.

Sincerely,

H. R. McCollum

Manager, Environmental Control

HRM/kb-95124 Enclosure

U. S. Steel Group

A unit of USX Corporation



